

# CNC - 50 HOUR PROGRAMMING COURSE





Fig. 126. Use of one single subprogram for the execution of multiple grooves




# CNC - 50 HOUR PROGRAMMING COURSE



Fig. 127. Profile described in the subprogram

```
N80 G0 X82 Z2
N90 G1 X6 F0.2
N100 G0 X80 Z2
N110 CYCLE62(, 2, "PROFILE1", "END1")
N120 CYCLE952("con_temp", "", 2301311, 0.1, 0, 0, 3, 0.1, 0.1, 0.5, 0.1, 0.1, 0
N130 G0 X200 Z200
```

Fig. 128. Insertion of fixed cycles in a program





# CNC - 50 HOUR PROGRAMMING COURSE



```
N80 G0 X82 Z2█  
N90 G1 X6 F0.2█  
N100 G0 X80 Z2█  
█  
N110 CYCLE62(, 2, "PROFILE1", "END1")█  
█  
N120 CYCLE952("con_temp", , "", 2301311, 0.1, 0, 0, 3, 0.1, 0.1, 0.5, 0.1, 0. █  
█  
N130 G0 X200 Z200█  
█
```

Modifying button

Fig. 129. Button for the modification of a cycle after its insertion





Fig. 130. HELP button on the control panel





# CNC - 50 HOUR PROGRAMMING COURSE

NC/WKS/CHAP\_15\_20/PRG\_19\_01

Stock removal - CYCLE952

Parameters, & code program			Parameters, ShopTurn program		
PRG	Name of the program to be generated		T	Tool name	
PL	Machining plane		D	Cutting edge number	
RP	Retraction plane – (only for machining direction, longitudinal, inner)	mm	F	Feedrate	mm/rev
SC	Safety clearance	mm	S / U	Spindle speed or constant cutting rate	m/min
F	Feedrate	*			
Residual	With subsequent				

Stock removal

PRG temp\_con

Residual mat. No

SC 1.000

F 0.100

Machining

Longitudinal

Outside

D 3.000

UX 0.500

UZ 0.100

DI 0.000

BL Cylinder

XD 0.000 inc

ZD 0.000 inc

Relief cuts No

Limit No

Current topic

Table of contents

Keyword index

Search

Full screen

Follow reference

Back to reference

Exit Help

Fig. 131. Help window with description of cycle parameters



Fig. 132. Start menu for the insertion of the fixed working cycles





# CNC - 50 HOUR PROGRAMMING COURSE




Fig. 133. Return to the EDIT menu to delete the cycles




	Horizontal softkey Cont. turn.
	Vertical softkey Contour.
	Vertical softkey Contour call.

Fig. 134. CYCLE62: procedure for the insertion of the cycle




# CNC - 50 HOUR PROGRAMMING COURSE



Fig. 135. CYCLE62: window for the insertion of the parameters

Parameter	Description
Labels	Select this option with the SELECT button; the profile is programmed in the main program; the beginning and the end of the block sequence is defined by the use of two labels.
LAB1	Name of the label for profile start (e.g. PROFILE1).
LAB2	Name of the label for profile end (e.g. END1).

Fig. 136. CYCLE62: label option





# CNC - 50 HOUR PROGRAMMING COURSE

Parameter	Description
Subprogram	Select this option with the SELECT button; the profile is programmed in a subprogram located in the workpiece directory or in the SUBPROGRAMS folder.
PRG	Name of the subprogram containing the profile (example for the name of the subprogram PROFILE1.SPF).

Fig. 137. CYCLE62: subprogram option

Parameter	Description
Labels in sub-program	Select this option with the SELECT button; the profile is programmed in a subprogram and limited by two labels for the beginning and the end.
PRG	Name of the subprogram containing the profile.
LAB1	Name of the label for profile start.
LAB2	Name of the label for profile end.

Fig. 138. CYCLE62: label in subprogram option

Parameter	Description
Contour name	Select this option with the SELECT button; the profile is defined by means of the graphic profile generator.
CON	Name of the saved contour.

Fig. 139. CYCLE62: profile name option



Fig. 140. Graphic profile generator



# CNC - 50 HOUR PROGRAMMING COURSE



	Horizontal softkey Cont. turn.
	Vertical softkey Stock removal.

Fig. 141. CYCLE952: procedure for the insertion of the cycle














Fig. 142. CYCLE952: window for the insertion of the parameters





# CNC - 50 HOUR PROGRAMMING COURSE

Parameter	Description
PRG	Name of the temporary program the cycle refers to in order to create and save the tool path. Various types of names can be used (e.g. temp_con, temporary contour).
SC	Safety distance for the approach of the tool used on the X-axis with diametral value and on the Z-axis with real value (example for a value: 1 mm).
F	Feedrate used by the tool during the roughing phase. The feedrate programmed in the finished profile of the workpiece is not taken into account in this case.
Machining	Type of tooling operation to carry out. Roughing of the workpiece (please select). Only finishing of the selected profile.
Longitudinal	For workpieces with proportions similar to a shaft.
Face	For workpieces with proportions similar to a flange.
Parallel to the contour	For workpieces already shaped as casting, molded parts or preworked parts.
Outside	For external profiles.
Inside	For internal profiles.
- RP	If internal, it expresses the return value in X.
 	Inversion of the cutting direction. The NC checks if this selection is compatible with the position of the cutting edge.
D	Pass depth (if it has a radial value in X).

	Adapts the pass trajectories to the profile to be roughed and levels the shoulders, thereby guaranteeing the possibility to leave a constant machining allowance on the whole profile (recommended selection).
	Exclusively performs straight trajectories leaving a stepped surface even in the presence of cones.
	Adapts the pass direction to the trajectories of the profile to be roughed by executing them only when the angle between the cutting edge and the profile exceeds the value determined by the machine data.
	Refers the distribution of the passes to the edges of the profile while maintaining the pass depth as constant as possible (to be used when, due to problems with chip control, it is preferable not to execute passes of shallow depth).
	The pass always starts with the set cutting depth and then adapts to the edges of the workpiece (allows the pre-emptive calculation of the pass number necessary to carry out the roughing operation).
	Constant cutting direction (recommended choice).
	Inclined cutting direction (prevents the craterization of the insert).
UX	Allowance to be left on the X-axes with radial value.
UZ	Allowance to be left on the Z-axes.
DI	Cutting length in millimeters after which the tool moves back in order to break the chip. If the value is zero, a continuous pass without chip breaking movements will be carried out.

BL	Description of the distribution of the material to be removed. <ul style="list-style-type: none"><li>- Cylinder: material quantity to be removed beyond the cylinder defined by the end points of the profile.</li><li>- Allowance: total quantity of material to be removed for shaped workpieces.</li><li>- Contour: specific definition of the profile of rough material to be removed.</li></ul>
XD	Further quantity of rough material in X (used for blank parts turning eccentrically).
ZD	Further quantity of rough material in Z (used for non-orthogonal faces on the Z-axis).
Relief cuts	With the SELECT button, select: <ul style="list-style-type: none"><li>- YES in order to execute the tooling operation of the parts on the shadow side of the profile.</li><li>- NO in order to rough the profile without taking into consideration the parts on the shadow side.</li></ul>
- FR	When selecting YES the cycle asks that a specific feedrate be entered for plunge cutting.
Limit	With the SELECT button, select: <ul style="list-style-type: none"><li>- YES in order to limit the material to be roughed in a certain area.</li><li>- NO in order to remove all the material.</li></ul>
- XA	When selecting YES the cycle asks that you enter the absolute coordinates limiting the area of the material to be removed.
- XB	
- ZA	
- ZB	

Fig. 143. CYCLE952: list of cycle parameters



# CNC - 50 HOUR PROGRAMMING COURSE





Fig. 144. External roughing of a workpiece with fixed cycle





# CNC - 50 HOUR PROGRAMMING COURSE




Fig. 145. Internal roughing of a workpiece with fixed cycle




 Turning	Horizontal softkey Turning.
 Thread	Vertical softkey Thread.  The following options are shown: Thread long.,                      Thread taper, Thread face,                      Thread chain.
 Thread long.	Vertical softkey Thread long.

Fig. 146. CYCLE99: procedure for the insertion of the cycle



# CNC - 50 HOUR PROGRAMMING COURSE

NC/WKS/CHAP\_15\_20/PRG\_20\_01

Thread longitudinal

Table **ISO metric**

Select **M 16**

P **2.000 mm/rev**

Machining **▽+▽▽▽**

**Degressive**

**External thread**

X0 **16.000**


Z0 **0.000**

Z1 **-29.400 abs**

LW **4.000**

LR **0.000**

H1 **1.227**

αP **30.000 °** 

D1 **0.300**

U **0.050**

NN **0**

UR **1.000**

Multiple **No**

αθ **0.000 °**





Fig. 147. CYCLE99: window for the insertion of the parameters







# CNC - 50 HOUR PROGRAMMING COURSE










1		ROUGHING TOOL	1	1	88.000	40.000	0.800	←	93.0	55	11.0
2											
3		OD GROOVING W.3MM	1	1	98.000	40.000	0.100		3.000		10.0
4											
5		CENTER DRILL D.6	1	1	100.000	24.000	6.000		118.0		
6											
7											
8											
9											
10											
11		AX. DRILL D.16	1	1	100.000	120.000	16.000		118.0		
12		ROUGH. BORING-BAR	1	1	86.000	92.000	0.400	←	93.0	55	8.0
13		FINISH. BORING-BAR	1	1	84.000	88.000	0.200	←	93.0	55	8.0
14		ID GROOV. W.3MM	1	1	92.000	75.000	0.100		3.000		8.0
15		ID THREADING	1	1	88.000	95.000	0.200				
16		AX. DRILL D.12	1	1	100.000	72.000	12.000		118.0		

Fig. 149. List of tools to be created and used in the test program





















500 - Roughing tool					
510 - Finishing tool					
520 - Plunge cutter					
540 - Threading tool					

Fig. 150. Choice of the position of the cutting edge

Tooling sequence	Tool	Operation	Cutting speed (m/min)	Feedrate (mm/rev)
1 <sup>st</sup>	T1 D1	External profile	100	0.18
2 <sup>nd</sup>	T3 D1	External grooves	78	0.1
3 <sup>rd</sup>	T5 D1	Center drilling	80	0.07
4 <sup>th</sup>	T16 D1	Hole D12	60	0.1
5 <sup>th</sup>	T12 D1	Int. roughing	70	-
6 <sup>th</sup>	T13 D1	Int. finishing	90	-
7 <sup>th</sup>	T14 D1	Int. groove	60	-
8 <sup>th</sup>	T15 D1	Int. threading	60	-

Fig. 151. Sequence of tooling operations and cutting parameters to use for the test





## A collection of 50 HOURS PRO books and tablets. The central focus is a large white book titled "50 HOURS PRO CNC" by "50 HOURS PRO". The cover features a large, stylized "CNC" logo composed of various national flags. To the left, a tablet displays the same "CNC" logo. To the right, another tablet displays the "CNC" logo. In the background, a stack of books is visible, with the top one being "50 HOURS PRO CNC". The books are arranged in a way that suggests a comprehensive set of materials for learning CNC.



Fig. 152. Drawing of the part to be created

# CNC - 50 HOUR PROGRAMMING COURSE




	Horizontal softkey Turning.
	Vertical softkey Groove. The following options are shown: <ul style="list-style-type: none"><li>- Groove with straight walls without chamfers and/or radii on the edges.</li><li>- Groove with possible straight walls with chamfers and/or radii on the edges.</li><li>- Groove on conical diameter.</li></ul>
	Choose the second option.

Fig. 153. CYCLE930: procedure for the insertion of the cycle




Fig. 154. CYCLE930: window for the insertion of the parameters





# CNC - 50 HOUR PROGRAMMING COURSE




Fig. 155. Programming example with the use of the groove cycle




	Horizontal softkey Drilling.
	Vertical softkey Drilling Reaming  The reaming cycle is similar to the drilling cycle, but it has the additional option to set a working feedrate to get into the hole and a faster rate to exit from the hole.
	Select Drilling.

Fig. 156. CYCLE82: procedure for the insertion of the cycle





# CNC - 50 HOUR PROGRAMMING COURSE




Fig. 157. CYCLE82: window for the insertion of the parameters





Fig. 158. Example of the programming of an axially drilled workpiece





# CNC - 50 HOUR PROGRAMMING COURSE




Fig. 159. Example of the programming of a radially drilled workpiece




Fig. 160. Programming example with modal activation of the cycle





# CNC - 50 HOUR PROGRAMMING COURSE



	Horizontal softkey Drilling.
	Vertical softkey Deep hole drilling.

Fig. 161. CYCLE83: procedure for the insertion of the cycle




Fig. 162. CYCLE83: window for the insertion of the parameters





# CNC - 50 HOUR PROGRAMMING COURSE




Fig. 163. Example of the programming of a drilled workpiece




	Horizontal softkey Drilling.
	Vertical softkey Thread.
	Vertical softkey Tapping.

Fig. 164. CYCLE84/840: procedure for the insertion of the cycle





# CNC - 50 HOUR PROGRAMMING COURSE




Fig. 165. CYCLE84/840: window for the insertion of the parameters




Fig. 166. Example of the programming of an axial tapping





# CNC - 50 HOUR PROGRAMMING COURSE




Fig. 167. Example of the programming of a radial tapping




	Horizontal softkey Turning.
	Vertical softkey Undercut.
	Vertical softkey Undercut thread.

Fig. 168. CYCLE940: procedure for the insertion of the cycle





Fig. 169. CYCLE940: window for the insertion of the parameters





# CNC - 50 HOUR PROGRAMMING COURSE




Fig. 170. Example of the programming of a thread undercut




Fig. 171. Angular orientation of the spindle for the creation of radial holes





# CNC - 50 HOUR PROGRAMMING COURSE

---




Fig. 172. Calculation of the feedrate expressed in degrees




Fig. 173. Calculation of the feedrate in simple cylindrical interpolation C-Z



# CNC - 50 HOUR PROGRAMMING COURSE




Fig. 174. Interpolation example with TRACYL





Fig. 175. Circumference on the reference diameter 'D'





# CNC - 50 HOUR PROGRAMMING COURSE




Fig. 176. Example of a frontal interpolation with TRANSMIT




Fig. 177. Position of the virtual system of Cartesian axes Y-X



# CNC - 50 HOUR PROGRAMMING COURSE




Fig. 178. Example of the programming of a simple interpolation Z-C








Fig. 179. Cylindrical interpolation with TRACYL



Fig. 180. Interpolation plane after TRACYL activation (reference diameter 60 mm)



# CNC - 50 HOUR PROGRAMMING COURSE




Fig. 181. Frontal interpolation with TRANSMIT



# CNC - 50 HOUR PROGRAMMING COURSE

Tooling sequence	Tool	Operation	Cutting speed (m/min)	Feedrate (mm/rev)
Tooling operation no. 1: use the roughing cycle				
1 <sup>st</sup>	T1 D1	External roughing	100	0.18
Tooling operation no. 2: program the finished profile by using ISO codes				
2 <sup>nd</sup>	T2 D1	External finishing	120	0.12
Tooling operation no. 3: use the cycle for undercuts, define the insert angle at 35°				
3 <sup>rd</sup>	T2 D1	Undercut	100	0.12
Tooling operation no. 4: use the threading cycle				
4 <sup>th</sup>	T4 D1	Threading M36x4	60	-
Tooling operation no. 5: use the ISO codes, execute center drilling up to Z-4				
5 <sup>th</sup>	T5 D1	Center drilling	80	0.08
Tooling operation no. 6: use the drilling cycle				
6 <sup>th</sup>	T6 D1	Hole D8.5	80	0.1
Tooling operation no. 7: use the rigid tapping cycle				
7 <sup>th</sup>	T7 D1	Tap M10	40	-
Tooling operation no. 8: use the function M70, calculate the feedrate in degrees per revolution				
8 <sup>th</sup>	T10 D1	Milling on circumference	35	0.06
Tooling operation no. 9: use the TRANSMIT function				
9 <sup>th</sup>	T9D1	Frontal milling	80	0.1

Fig. 182. Sequence of tooling operations and cutting parameters to use for the test





# CNC - 50 HOUR PROGRAMMING COURSE





Fig. 183. Drawing of the part to be created



# CNC - 50 HOUR PROGRAMMING COURSE





Fig. 184. Part created by the support program for the 3rd test





# CNC - 50 HOUR PROGRAMMING COURSE




Fig. 185. 1: engraving on plane G19, 2: engraving on plane G17



	Horizontal softkey Milling.
	Vertical softkey Engraving.

Fig. 186. CYCLE60: procedure for the insertion of the cycle



# CNC - 50 HOUR PROGRAMMING COURSE




Fig. 187. CYCLE60: window for the insertion of the parameters





Fig. 188. CYCLE82: window for the insertion of the parameters





# CNC - 50 HOUR PROGRAMMING COURSE

---



Fig. 189. Use of the engraving cycle to write on the circumference



Fig. 190. Use of the engraving cycle to write on the front face of the workpiece



# CNC - 50 HOUR PROGRAMMING COURSE

	JOG				
R variables					R variables
R 0	0	R 20	0	R 40	0
R 1	0	R 21	0	R 41	0
R 2	0	R 22	0	R 42	0
R 3	0	R 23	0	R 43	0
R 4	0	R 24	0	R 44	0
R 5	0	R 25	0	R 45	0
R 6	0	R 26	0	R 46	0
R 7	0	R 27	0	R 47	0
R 8	0	R 28	0	R 48	0
R 9	0	R 29	0	R 49	0
R 10	0	R 30	0	R 50	0
R 11	0	R 31	0	R 51	0
R 12	0	R 32	0	R 52	0
R 13	0	R 33	0	R 53	0
R 14	0	R 34	0	R 54	0
R 15	0	R 35	0	R 55	0
R 16	0	R 36	0	R 56	0
R 17	0	R 37	0	R 57	0
R 18	0	R 38	0	R 58	0
R 19	0	R 39	0	R 59	0
					Search
					SD
Tool list	Tool wear	Maga-zine	Work offset	R User variable	Setting data

Fig. 191. Page for the calculation variables 'R'

	OFFSET.
	Horizontal softkey User variables.
	Vertical softkey R variables.

Fig. 192. Procedure for access to the 'R' variables page





# CNC - 50 HOUR PROGRAMMING COURSE

The first letter after \$ stands for:

\$M	Machine data.
\$S	Setting data.
\$T	Tool management data.
\$P	Programmed values.
\$A	Current values.
\$V	Service data.

Fig. 193. Meaning of the first letter in the name of system variables

The second letter after \$ stands for:

N	Global NCK.
C	Specification for channels.
A	Specification for axis.

Fig. 194. Meaning of the second letter in the name of system variables

+	Sum.
-	Subtraction.
*	Multiplication.
/	Division.

Fig. 195. Arithmetic functions

SIN(...)	Sine of the angle.
COS(...)	Cosine of the angle.
TAN(...)	Tangent of the angle.
ASIN(...)	Arcsine.

ACOS(...)	Arccosine.
ATAN2(1°, 2°)	Arctangent with argument arcsine (1°) and argument arccosine (2°).

Fig. 196. Trigonometric functions




Fig. 197. Calculation scheme of the trigonometric functions

TRUNC	Whole part.
ROUND	Rounding to whole number.

Fig. 198. Result management functions




# CNC - 50 HOUR PROGRAMMING COURSE

The screenshot displays the Siemens CNC MDI (Manual Data Entry) window. The interface is divided into several sections:

- Top Bar:** Includes a 'Reset' button and the 'SIEMENS' logo.
- Machine Status:** Shows 'Machine' and 'Position [mm]' for MX1 and M21, both at 500.000. It also displays 'MSP1' and 'MSP3' at 0.000°.
- Parameters:** Includes 'T,F,S' (T), 'F' (0.000 mm/min), 'S1' (0), and 'Master' (0).
- MDI Area:** Contains the code 'R0=ROUND(10.52)'.
- Right Sidebar:** Features buttons for 'G functions', 'Auxiliary functions', 'Delete blocks', and 'Act. values Machine'.
- Bottom Bar:** Includes a status message 'Invalid tool name: ROUGHING\_T88 A' and buttons for 'Load MDI', 'Save MDI', and 'Prog. ctrl.'.

Fig. 199. Window for manual data entry





# CNC - 50 HOUR PROGRAMMING COURSE





Fig. 200. Drawing of a workpiece family



# CNC - 50 HOUR PROGRAMMING COURSE




Fig. 201. CYCLE940 with parameter defined by means of the variable R1





Fig. 202. CYCLE99 with parameter defined by the variable R1 in a formula





# CNC - 50 HOUR PROGRAMMING COURSE

---




Fig. 203. Execution of equidistant holes distributed over 360°



Fig. 204. Execution of a series of holes with constant lead, but not distributed over 360°



# CNC - 50 HOUR PROGRAMMING COURSE

---





Fig. 205. Part executed with the algorithm entered in the program PRG\_31\_04





# CNC - 50 HOUR PROGRAMMING COURSE

---





Fig. 206. The same right hand rule applies both to the lathe and to the mill.



# CNC - 50 HOUR PROGRAMMING COURSE




Fig. 207. Positive direction of the axes: the arrows show the movements of the tool compared to the workpiece




Fig. 208. Vertical mill





Fig. 209. Horizontal mill





# CNC - 50 HOUR PROGRAMMING COURSE

---




Fig. 210. C-axis in a machining center



Fig. 211. B-axis in a machining center





# CNC - 50 HOUR PROGRAMMING COURSE

---




Fig. 212. CAM-generated profile for five-axis machining center




Fig. 213. Programming scheme on plane G17





# CNC - 50 HOUR PROGRAMMING COURSE




Fig. 214. Position of the machine zero point and values to enter into the zero offset function for the definition of the part zero point




Fig. 215. Use of TRANS: 1: in a lathe; 2: in a machining center





# CNC - 50 HOUR PROGRAMMING COURSE

---





Fig. 216. 1:Point moved by the NC; 2:Offset value of a mill on the Z-axis






# CNC - 50 HOUR PROGRAMMING COURSE

---



Fig. 218. Start-up of the mill in the training software



# CNC - 50 HOUR PROGRAMMING COURSE




Fig. 219. Page for the selection of the tools directly from the magazine





Fig. 220. Completion of the direct tool call instruction in the program





# CNC - 50 HOUR PROGRAMMING COURSE

Blank part:	Cylinder
XA:	Cylinder diameter.
ZA:	Position of the upper face of the workpiece referring to the part zero point.
ZI - absolute: - incremental:	Distance from the lower face of the workpiece: <b>referring to the part zero point.</b> <b>referring to the upper face.</b>

Fig. 221. Description of the blank part dimensions: CYLINDER

Blank part:	Pipe
XA:	External diameter of the pipe.
XI:	Internal diameter of the pipe.


Fig. 222. Description of the blank part dimensions: PIPE

Blank part:	Block Centered
W:	Side of the rectangle positioned along the Y-axis.
L:	Side of the rectangle positioned along the X-axis.

Fig. 223. Description of the blank part dimensions: BLOCK CENTERED

Blank part:	Block
X0:	Coordinate X of the edge referring to the part zero point.
Y0:	Coordinate Y of the edge referring to the part zero point.
X1:	Coordinate X of the opposite edge referring to the part zero point (abs.) or to the first edge (incr.).
Y1:	Coordinate Y of the opposite edge referring to the part zero point (abs.) or to the first edge (incr.).

Fig. 224. Description of the workpiece dimensions: BLOCK



# CNC - 50 HOUR PROGRAMMING COURSE




Fig. 225. Description of the blank part dimensions: BLOCK

Blank part:	N Corner
N:	Number of edges of the polygon.
SW:	Dimension of the polygon's key (available only for polygons with even number of edges).

Fig. 226. Description of the workpiece dimensions: N CORNER





# CNC - 50 HOUR PROGRAMMING COURSE





Fig. 227. Drawing of the part to be created



# CNC - 50 HOUR PROGRAMMING COURSE




Fig. 228. Creation of the external profile





Fig. 229. Roughing of the internal profile





# CNC - 50 HOUR PROGRAMMING COURSE




Fig. 231. Data entered in drilling cycle




Fig. 230. Finishing of the internal profile



# CNC - 50 HOUR PROGRAMMING COURSE

---





Fig. 232. Graphic 3D image of the finished part



Fig. 233. Discordant cutting direction (left) and concordant cutting direction (right)





# CNC - 50 HOUR PROGRAMMING COURSE




Fig. 234. Chip section area




Fig. 235. Relative movement between cutter and workpiece with discordant feed direction



# CNC - 50 HOUR PROGRAMMING COURSE




Fig. 236. Cutting forces with discordant feed direction





Fig. 237. Relative movement between cutter and workpiece with concordant feed direction





# CNC - 50 HOUR PROGRAMMING COURSE




Fig. 238. Cutting forces with concordant feed direction




Fig. 239. Cutting forces with concordant feed direction



# CNC - 50 HOUR PROGRAMMING COURSE




Fig. 240. Cutting forces with concordant feed direction





Fig. 241. Conventional and climb face milling





# CNC - 50 HOUR PROGRAMMING COURSE

---





Fig. 242. Three-dimensional representation of the workpiece



# CNC - 50 HOUR PROGRAMMING COURSE





Fig. 243. Drawing of the part to create





# CNC - 50 HOUR PROGRAMMING COURSE

---





Fig. 244. Three-dimensional representation of the workpiece



# CNC - 50 HOUR PROGRAMMING COURSE





Fig. 245. Drawing of the part to create





# CNC - 50 HOUR PROGRAMMING COURSE

---




Fig. 246. Three-dimensional representation of the workpiece





Fig. 247. Definition of a point in plane G17 using polar coordinates



# CNC - 50 HOUR PROGRAMMING COURSE





Fig. 248. Drawing of the part to create





# CNC - 50 HOUR PROGRAMMING COURSE

---





Fig. 249. Three-dimensional representation of the workpiece



# CNC - 50 HOUR PROGRAMMING COURSE





Fig. 250. Drawing of the part to create







# CNC - 50 HOUR PROGRAMMING COURSE

---





Fig. 253. Drawing of the part to create





# CNC - 50 HOUR PROGRAMMING COURSE




Fig. 253. Drawing of the part to create

