

CNC - BASIC PROGRAMMING COURSE



Fig. 1. Optional control panel for SinuTrain





Fig. 2. Lathe with 3 axes and driven tools



CNC - BASIC PROGRAMMING COURSE



Fig. 2.1 Milling machine with 3 axes

Hardware:	Processor 2 GHz, RAM 4 GB, Internet connection, USB data port
Disc Capacity:	Approx. 3.3 GB for full installation
Operating System:	Windows 7 SP1 (32 and 64 Bit) (no: Starter, Web Edition, Embedded) Windows 8.1 (32 and 64 Bit) (no: RT) Windows 10 (64 Bit) (no: Mobile, Mobile Enterpr.)
User Settings:	PC administrator rights required for installation and use
License:	The machines examined in the course (DEMO-Lathe and DEMO-Milling Machine) do not require any license

Fig. 3. Minimum PC requirements

Username:	Password:
.....

Fig. 4. Personal access data to Siemens website



CNC - BASIC PROGRAMMING COURSE




Fig. 5. Starting window of the simulation program



Fig. 6. Buttons for the selection of the operating environments




Fig. 7. Buttons for cursor movement and data entry



CNC - BASIC PROGRAMMING COURSE





Fig. 8. Technical drawing of the introductory workpiece of the course



CNC - BASIC PROGRAMMING COURSE




Fig. 9. Organization of the programs on the PROGRAM MANAGER page




Fig. 10. Dialog box for the import of tooling data



CNC - BASIC PROGRAMMING COURSE




Fig. 11. Window for the confirmation and overwriting of the tool data

Blank part:	Shape of the blank part (e.g. cylinder)
XA:	External diameter of the blank part (e.g. 80 mm).
ZA:	Value of the machining allowance on the front face of the blank part (e.g. 0.5 mm).
ZI:	Length of the blank part. If by pushing SELECT you select ABSOLUTE (recommended), the length refers to the part zero point, if INCREMENTAL, the length refers to the front face of the part, machining allowance included.
ZB:	Extension of the face of the blank part from the jaws of the chuck. For the selection of absolute or incremental the same applies as for ZI.

Fig. 12. Description of the blank part dimensions



CNC - BASIC PROGRAMMING COURSE




Fig. 13. Program opened and ready for simulation




Fig. 14. Display options for the workpiece



CNC - BASIC PROGRAMMING COURSE




Fig. 15. Execution of the graphic simulation in single block mode




Fig. 16. Activation and setting of the potentiometers for the execution of the program in automatic cycle



CNC - BASIC PROGRAMMING COURSE




Fig. 17. Right-hand rule: definition of the axes and their positive motion according to ISO Standards. The positive motion is always determined in relation to the moving path of the tool on the workpiece.





Fig. 18. Solid of revolution around the Z-axis of the profile described on the plane X-Z



CNC - BASIC PROGRAMMING COURSE




Fig. 19. Angular orientation of the spindle for the creation of radial holes





Fig. 20. Example of a cylindrical interpolation C-Z



CNC - BASIC PROGRAMMING COURSE




Fig. 21. Example of a frontal interpolation C-X





Fig. 22. Right-hand rule to determine the positive motion of the rotating axes



CNC - BASIC PROGRAMMING COURSE




Fig. 23. C-axis positive programming direction and real movement of the workpiece





Fig. 24. Milling of a key using the real Y-axis



CNC - BASIC PROGRAMMING COURSE




Fig. 25. Universal lathe with B-axis





Fig. 26. Lathe with A-axis



CNC - BASIC PROGRAMMING COURSE





Fig. 27. Programming scheme



CNC - BASIC PROGRAMMING COURSE





Fig. 28. Traditional lathe where the tool moves on the workpiece



Fig. 29. Lathe with real movement of the Z-axis and of the X-axis on the workpiece



CNC - BASIC PROGRAMMING COURSE





Fig. 30. Technical drawing created by the program PRG_04_01



CNC - BASIC PROGRAMMING COURSE





Fig. 31. Technical drawing of the part to create in program EX_04_01



CNC - BASIC PROGRAMMING COURSE




Fig. 32. Display of the PROGRAM MANAGER





Fig. 33. File properties window



CNC - BASIC PROGRAMMING COURSE

Block	Word	Word	Word	; Comment
Block	N10	G0	X20	; First block
Block	N20	G2	Z37	; Second block
Block	N30	G91
Block	N40	
Block	N50	M30	...	; End of program

Fig. 34. Name of the elements constituting the program

Address	Meaning
N	Address of block number
10	Block number
G	Preparatory function
X, Y, Z	Path information
F	Feed rate
S	Number of revolutions or cutting speed
T	Tool position
D	Number of tool corrector
M	Auxiliary function

Fig. 35. Meaning of some addresses

Name	Meaning
G0	Rapid traverse motion
G1	Linear interpolation
G2	Circular interpolation clockwise
G3	Circular interpolation counterclockwise
G33	Thread cutting with constant lead
G331	Rigid tapping
G332	Return (rigid tapping)
G34	Thread cutting with variable lead
G35	Thread with decreasing lead

Fig. 36. Group 1: Motion commands

Name	Meaning
G17	Plane selection 1st - 2nd geometry axis (X-Y)
G18	Plane selection 3rd - 1st geometry axis (Z-X)
G19	Plane selection 2nd - 3rd geometry axis (Y-Z)

Fig. 37. Group 6: Plane selection

Name	Meaning
G40	Deactivation of the tool radius compensation
G41	Activation of the tool radius compensation left of contour
G42	Activation of the tool radius compensation right of contour

Fig. 38. Group 7: Tool radius compensation

Name	Meaning
G500	Cancel all adjustable frames G54 - G57 if no value in G500
G54	Settable zero offset
G55	Settable zero offset
G56	Settable zero offset
G57	Settable zero offset

Fig. 39. Group 8: Settable zero offset (frame)

Name	Meaning
G60	Velocity reduction, precise stop
G64	Continuous path mode

Fig. 40. Group 10: Precise stop – continuous path mode

Name	Meaning
G70	Selects English units (inches and feet)
G71	Selects metric units (millimeter and meter)

Fig. 41. Group 13: Workpiece dimensioning inch/metric

Name	Meaning
G90	Absolute coordinate system
G91	Incremental coordinate system

Fig. 42. Group 14: Absolute/incremental coordinate system

Name	Meaning
G94	Linear feed mm/min or inch/min
G95	Rotational feed in mm/rev or inch/rev
G96	Constant cutting speed in m/min or feet/min
G97	Constant number of revolutions in rev./min

Fig. 43. Group 15: Feed rate and rotation type




CNC - BASIC PROGRAMMING COURSE

Name	Meaning
G4	Dwell time preset
G9	Exact stop only in the block where it is programmed
G53	Suppression of current frame

Fig. 44. Self-deleting instructions

Name	Meaning
M0	Programmed stop
M1	Optional stop activated by the control panel
M3	Spindle clockwise
M4	Spindle counterclockwise
M5	Spindle stop
M6	Tool change (if provided)
M8	Cooling liquid activation
M9	Cooling liquid stop
M30	End of program and return to beginning
M17	End of subroutine and return to main program
M40	Automatic gear change (when provided)
M41	Gear stage 1 (if provided)
M42	Gear stage 2 (if provided)
M43	Gear stage 3 (if provided)
M44	Gear stage 4 (if provided)
M45	Gear stage 5 (if provided)
M70	Spindle with transition to functioning as an axis

Fig. 45. Auxiliary or miscellaneous functions



CNC - BASIC PROGRAMMING COURSE




Fig. 46. Start of the simulation in order to analyze the program






Fig. 47. Automatic block numbering screen



CNC - BASIC PROGRAMMING COURSE



The screenshot shows a CNC control interface with a program editor. The program text is as follows:

```
NC/WKS/CHAP_05/PRG_05_01 13
; blank part dimensions:
; XA = 80 bar diameter
; ZA = 0 machining allowance on front face
; ZI = -200 length of finished part
; ZB = -150 extension from jaws
;
WORKPIECE(,,, "CYLINDER", 0, 0, -200, -150, 80)
;
G18 G54 G90 ;G54 PART ZERO POINT SETTING
G0 X400 Z500
M8
SETMS(1)
;
T1 D1 ; LEFT HAND ROUGHING TOOL
G95 S1800 M4 ; SPINDLE ROTATION AND FEEDRATE SETTING
F0.2 ; FEEDRATE SETTING
G0 X82 Z0 ; APPROACH
G1 X-1; TOOLING OPERATION: FACING
G0 X66 Z2 ; DISENGAGEMENT
G0 Z0.5 ; APPROACH
```

The interface includes a top bar with icons for Jog and a menu bar with options like View, Mold mak. view, Renumbering, Open further program, Settings, and Exit. A bottom toolbar contains icons for Edit, Drilling, Turning, Cont. turn., Milling, Various, Simulation, and Execute.

Fig. 48. Program without block numbers




Fig. 49. Machine coordinate system: point moved by the NC referring to the machine zero point



CNC - BASIC PROGRAMMING COURSE





Fig. 50. 1: Spindle nose ; 2: chuck with three jaws ; 3: Elastic collet for external hold;
4: Elastic expansion collet for internal hold of the workpiece



CNC - BASIC PROGRAMMING COURSE




Fig. 51. Workpiece coordinate system: tool tip referring to the part zero point





Fig. 52. Definition of the part zero point



CNC - BASIC PROGRAMMING COURSE



Work offset - G54 ... G57 [mm]

		X	Z	SP1	SP3	Workpiece zero p't
G54		0.000	200.000	0.000	0.000	
	Fine	0.000	0.000	0.000	0.000	Active
G55		0.000	0.000	0.000	0.000	
	Fine	0.000	0.000	0.000	0.000	Overview
G56		0.000	0.000	0.000	0.000	
	Fine	0.000	0.000	0.000	0.000	
G57		0.000	0.000	0.000	0.000	Base
	Fine	0.000	0.000	0.000	0.000	

Details

Tool list Tool wear Magazine Work offset User variable Setting data

Fig. 53. Table of work offsets




Fig. 54. Tool offset values



CNC - BASIC PROGRAMMING COURSE





Fig. 55. Page for manual data entry



CNC - BASIC PROGRAMMING COURSE





Fig. 56. Buttons for the selection of the continuous manual feed



CNC - BASIC PROGRAMMING COURSE



Fig. 57. Buttons for the selection of the manual feed by incrementation





Fig. 58. Touch-off position of the part face in the workpiece coordinate system



CNC - BASIC PROGRAMMING COURSE




Fig. 59. Touch-off position of the part face in the machine coordinate system




Fig. 60. Current position of the tool after activation of the workpiece coordinate system programmed in MDA



CNC - BASIC PROGRAMMING COURSE





Fig. 61. Page for the automatic offset by touching the workpiece

Loc.	Type	Tool name	ST	D	Length X	Length Z	Radius	Loc. leng
1	ROUGHING TOOL	1	1	88.000	48.000	0.000	93.0	55 11.8
2	FINISHING TOOL	1	1	94.000	48.000	0.200	93.0	55 11.8
3	OD GROOVING W.3MM	1	1	98.000	48.000	0.100	3.000	18.0
4	OD GROOVING W.3MM	1	2	98.000	37.000	0.100	3.000	18.0
5	OD THREADING	1	1	88.000	46.000	0.200		
6	CENTER DRILL D.6	1	1	100.000	24.000	6.000	118.0	
7	AX. DRILL D.8.5	1	1	100.000	56.000	8.500	118.0	
8	AX. TAPPING M18	1	1	100.000	81.000	10.000	1.500	
9	RAD. DRILL D.6	1	1	122.000	0.000	6.000	118.0	
10	AX. END MILL D.16	1	1	100.000	80.000	16.000	3	
11	RAD. END MILL D.3	1	1	134.000	0.000	3.000	2	
12	AX. DRILL D.16	1	1	100.000	120.000	16.000	118.0	
13	ROUGH. BORING-BAR	1	1	86.000	92.000	0.400	93.0	55 8.0
14	FINISH. BORING-BAR	1	1	84.000	88.000	0.200	93.0	55 8.0
15	ID GROOV. W.3MM	1	1	92.000	75.000	0.100	3.000	8.0
16	ID THREADING	1	1	88.000	95.000	0.200		
17	AX. DRILL D.12	1	1	100.000	72.000	12.000	118.0	

Fig. 62. Tool list page



CNC - BASIC PROGRAMMING COURSE

3		OD GROOVING W.3MM	1	1	98.000	40.000	0.100	3.000	10.0
		OD GROOVING W.3MM	1	2	98.000	37.000	0.100	3.000	10.0




Fig. 63. Double corrector used for a 3 mm grooving tool



















MAGAZIN1									
Loc.	Type	Tool name	ST	D	ΔLength X	ΔLength Z	ΔRadius	T C	
1		ROUGHING TOOL	1	1	0.000	0.000	0.000		
2		FINISHING TOOL	1	1	0.000	0.000	0.000		
3		OD GROOVING W.3MM	1	1	0.000	0.000	0.000		
		OD GROOVING W.3MM	1	2	0.000	0.000	0.000		
4		OD THREADING	1	1	0.000	0.000	0.000		
5		CENTER DRILL D.6	1	1	0.000	0.000	0.000		
6		AX. DRILL D.8.5	1	1	0.000	0.000	0.000		
7		AX. TAPPING M10	1	1	0.000	0.000	0.000		
8		RAD. DRILL D.6	1	1	0.000	0.000	0.000		
9		AX. END MILL D.16	1	1	0.000	0.000	0.000		
10		RAD. END MILL D.3	1	1	0.000	0.000	0.000		
11		AX. DRILL D.16	1	1	0.000	0.000	0.000		
12		ROUGH. BORING-BAR	1	1	0.000	0.000	0.000		
13		FINISH. BORING-BAR	1	1	0.000	0.000	0.000		
14		ID GROOV. W.3MM	1	1	0.000	0.000	0.000		
15		ID THREADING	1	1	0.000	0.000	0.000		
16		AX. DRILL D.12	1	1	0.000	0.000	0.000		

Fig. 64. Tool correction page



CNC - BASIC PROGRAMMING COURSE



The screenshot shows the CNC tool list interface. At the top, there are icons for 'JOG' and a 'Tool list' button. The main table has columns: Loc., Type, Tool name, ST, D, Length X, Length Z, Radius, and Loc. leng. The first row (Loc. 1) is highlighted in orange and contains the text 'ROUGHING TOOL'. To the right of the table, there are buttons for 'Tool measure', 'Edges', 'Unload', and 'Magazine selection'. At the bottom, there is a navigation bar with icons for 'Tool list', 'Tool wear', 'Magazine', 'Work offset', 'User variable', and 'Setting data'.

Loc.	Type	Tool name	ST	D	Length X	Length Z	Radius	Loc. leng
1		ROUGHING TOOL	1	1	88.000	40.000	0.000	93.0 55 11.0
2		FINISHING TOOL	1	1	94.000	40.000	0.200	93.0 55 11.0
3		OD GROOVING W.3MM	1	1	98.000	40.000	0.100	3.000 10.0
4		OD GROOVING W.3MM	1	2	98.000	37.000	0.100	3.000 10.0
5		OD THREADING	1	1	88.000	46.000	0.200	
6		CENTER DRILL D.6	1	1	100.000	24.000	6.000	118.0
7		AX. DRILL D.8.5	1	1	100.000	56.000	8.500	118.0
8		AX. TAPPING M10	1	1	100.000	81.000	10.000	1.500
9		RAD. DRILL D.6	1	1	122.000	0.000	6.000	118.0
10		AX. END MILL D.16	1	1	100.000	80.000	16.000	3
11		RAD. END MILL D.3	1	1	134.000	0.000	3.000	2
12		AX. DRILL D.16	1	1	100.000	120.000	16.000	118.0
13		ROUGH. BORING-BAR	1	1	86.000	92.000	0.400	93.0 55 8.0
14		FINISH. BORING-BAR	1	1	84.000	88.000	0.200	93.0 55 8.0
15		ID GROOV. W.3MM	1	1	92.000	75.000	0.100	3.000 8.0
16		ID THREADING	1	1	88.000	95.000	0.200	
17		AX. DRILL D.12	1	1	100.000	72.000	12.000	118.0
18		RAD. DRILL D.4	1	1	114.000	0.000	4.000	118.0
19		RAD. TAPPING M5	1	1	106.000	0.000	5.000	0.000
20								

Fig. 65. Impossible to create a new tool when an already existing tool is selected



The screenshot shows the CNC tool list interface. At the top, there are icons for 'JOG' and a 'Tool list' button. The main table has columns: Loc., Type, Tool name, ST, D, Length X, Length Z, Radius, and Loc. leng. The row for location 20 is highlighted in orange and is currently empty. To the right of the table, there are buttons for 'New tool', 'Edges', 'Unload', and 'Magazine selection'. At the bottom, there is a navigation bar with icons for 'Tool list', 'Tool wear', 'Magazine', 'Work offset', 'User variable', and 'Setting data'.

Loc.	Type	Tool name	ST	D	Length X	Length Z	Radius	Loc. leng
5		CENTER DRILL D.6	1	1	100.000	24.000	6.000	118.0
6		AX. DRILL D.8.5	1	1	100.000	56.000	8.500	118.0
7		AX. TAPPING M10	1	1	100.000	81.000	10.000	1.500
8		RAD. DRILL D.6	1	1	122.000	0.000	6.000	118.0
9		AX. END MILL D.16	1	1	100.000	80.000	16.000	3
10		RAD. END MILL D.3	1	1	134.000	0.000	3.000	2
11		AX. DRILL D.16	1	1	100.000	120.000	16.000	118.0
12		ROUGH. BORING-BAR	1	1	86.000	92.000	0.400	93.0 55 8.0
13		FINISH. BORING-BAR	1	1	84.000	88.000	0.200	93.0 55 8.0
14		ID GROOV. W.3MM	1	1	92.000	75.000	0.100	3.000 8.0
15		ID THREADING	1	1	88.000	95.000	0.200	
16		AX. DRILL D.12	1	1	100.000	72.000	12.000	118.0
17		RAD. DRILL D.4	1	1	114.000	0.000	4.000	118.0
18		RAD. TAPPING M5	1	1	106.000	0.000	5.000	0.000
19								
20								

Fig. 66. Selection of an empty location for the creation of a new tool




CNC - BASIC PROGRAMMING COURSE



0	EXAMPLE	1	1	80.000	40.000	0.100	3.000	10.0
---	---------	---	---	--------	--------	-------	-------	------

Fig. 68. Creation of a new tool

Fig. 67. Selection of the type of new tool to be created and position of the cutting edge



CNC - BASIC PROGRAMMING COURSE




Fig. 69. Saving of tooling data





Fig. 70. Window for the saving of tooling data



CNC - BASIC PROGRAMMING COURSE




Fig. 71. Distance traveled by the tool in one revolution





Fig. 72. Distance traveled by the tool in one minute with rotating workpiece

$$C_s = \frac{D \times \pi \times RPM}{1000} \quad \frac{\text{m}}{\text{min}}$$

Fig. 73. Formula for the calculation of the cutting speed



CNC - BASIC PROGRAMMING COURSE




Fig. 74. Name of the spindles shown on the "current position" page




Fig. 75. Inverse formula for the calculation of the number of revolutions



CNC - BASIC PROGRAMMING COURSE




Fig. 76. Graph for the evolution of cutting speed at variation of working diameter, at constant number of revolutions





Fig. 77. Graph for the cutting speed trend beyond the number of revolutions threshold



CNC - BASIC PROGRAMMING COURSE

Working diameter (mm)	Number of revolutions (r/min)	Cutting speed (m/min)
50	764	120
62	140
19	85
5	100
55	1200
8	1200
62	650
.....	4500	100
.....	2000	40
.....	2000	220

Fig. 78. Exercise for the calculation of the cutting speed, the number of revolutions and the diameter from which the cutting speed begins to decrease




Fig. 79. Creation of a new program



CNC - BASIC PROGRAMMING COURSE

Cut length (mm)	Feed rate (mm/rev)	Number of revolutions (rpm)	Time necessary (seconds)
60	0.3	840
60	0.12	1100
24	0.1	1260
18	0.06	780
22	0.14	1530
80	0.18	2100
66	0.05	1400
43	0.25	600

Fig. 80. Calculation exercises for the time needed for the tool to execute a pass





Fig. 81. Saving of folders and programs in an external memory



CNC - BASIC PROGRAMMING COURSE





Fig. 82. Origin of the axes in the absolute coordinate system referring to the part zero



CNC - BASIC PROGRAMMING COURSE





Fig. 83. Design values referring to the part zero point.



CNC - BASIC PROGRAMMING COURSE




Fig. 84. Origin of the axes in the incremental coordinate system





Fig. 85. Trajectory of rapid approach with the functions RTLION and RTLIOF



CNC - BASIC PROGRAMMING COURSE




Fig. 86. Movement of the tool along the Z-axis





Fig. 87. Linear interpolation with tool moving along the axes X and Z



CNC - BASIC PROGRAMMING COURSE




Fig. 88. Execution of a threading in multiple passes with G33





Fig. 89. Lead value to be programmed in a conical thread executed with G33



CNC - BASIC PROGRAMMING COURSE





Fig. 90. Example of the programming of an external turning



CNC - BASIC PROGRAMMING COURSE





Fig. 91. Elimination of the facing witness mark



CNC - BASIC PROGRAMMING COURSE





Fig. 92. Example of the programming of a threaded workpiece



CNC - BASIC PROGRAMMING COURSE




Fig. 93. Round between two line by means of the RND function





Fig. 94. Round between a line and a circle arc by means of the RND function



CNC - BASIC PROGRAMMING COURSE




Fig. 95. Chamfer executed between two lines by means of the function CHR or CHF





Fig. 96. Scheme for the definition of the angle by means of the function ANG



CNC - BASIC PROGRAMMING COURSE





Fig. 97. Programming of a profile by means of the functions CHR, FRCM and ANG



CNC - BASIC PROGRAMMING COURSE

Previous program created by programming the arrival point coordinates.	New program created by the direct programming of chamfers and angles.
<pre>;FINISHING OF THE PROFILE T2 D1 G95 S1800 M4 G0 X30 Z2 G1 Z0 F0.1 G1 X32 Z-1 G1 Z-22 G1 X40 Z-38 G1 X46 G1 X48 Z-39 G1 Z-60 G1 X58 G1 X60 Z-61 G1 Z-62 G1 X61 G0 X200 G0 Z200 M30</pre>	<pre>;FINISHING OF THE PROFILE T2 D1 G95 S1800 M4 G0 X26 Z2 G1 Z0 F0.1 G1 X32 CHR=1 FRCM=0.04 G1 Z-22 G1 Z-38 ANG=166 G1 X48 CHR=1 G1 Z-60 G1 X60 CHR=1 G1 Z-62 G1 X61 G0 X200 G0 Z200 M30</pre>

Fig. 98. Comparison between the two programs which create the same profile: in the left column by means of the point to point programming, in the right column by using the direct programming functions CHR, FRCM and ANG




Fig. 99. Page for entering the blank part data



CNC - BASIC PROGRAMMING COURSE





Fig. 100. Enter the missing data for the execution of this profile



CNC - BASIC PROGRAMMING COURSE




Fig. 101. G2 : circular interpolation in clockwise direction





Fig. 102. G3 : circular interpolation in counterclockwise direction



CNC - BASIC PROGRAMMING COURSE





Fig. 103. Programming of an arc by means of the radius center coordinates



CNC - BASIC PROGRAMMING COURSE




Fig. 104. Functions for the definition of the working plane





Fig. 105. Round between a radius and the following line by means of G2 and RND



CNC - BASIC PROGRAMMING COURSE




Fig. 106. Chamfer between a radius and the following line by means of G2 and CHR






Fig. 107. Use of the function G3



CNC - BASIC PROGRAMMING COURSE

14095



Channel 1: Block N100 radius for circle programming too small

Fig. 108. Type of alarm displayed in the event of a programming error in a radius







Tool list											MAGAZIN
Loc.	Type	Tool name	ST	D	Length X	Length Z	Ø		Tip angle		
1		ROUGHING TOOL	1	1	88.000	40.000	0.800	←	93.0	55	11.0
2		FINISHING TOOL	1	1	94.000	40.000	0.200	←	93.0	55	11.0
3		OD GROOVING W.3MM	1	1	98.000	40.000	0.100		3.000		10.0
4		OD THREADING	1	1	88.000	46.000	0.200				
5		CENTER DRILL D.6	1	1	100.000	24.000	6.000		118.0		
6		AX. DRILL D.8.5	1	1	100.000	56.000	8.500		118.0		

Fig. 109. List of tools to be created and used in the test program

Tooling sequence	Tool	Operation	Cutting speed (m/min)	Feed rate (mm/rev)
1 st	T1 D1	Roughing	100	0.18
2 nd	T2 D1	Finishing	120	0.12
3 rd	T3 D1	Groove	78	0.1
4 th	T4 D1	Threading	60	-
5 th	T5 D1	Center drilling	80	0.08
6 th	T6 D1	Hole D8.5	80	0.1

Fig. 110. Sequence of tooling operations and cutting parameters to use in the test



CNC - BASIC PROGRAMMING COURSE





Fig. 111. Drawing of the part to create



CNC - BASIC PROGRAMMING COURSE




Fig. 112. Offset points on the X-axis and Z-axis with tool radius





Fig. 113. Point moved by the NC after the tool offset



CNC - BASIC PROGRAMMING COURSE




Fig. 114. Absence of changes due to the tool radius on diameters and shoulders





Fig. 115. Dimensional error caused by the insert radius during the execution of conical turnings



CNC - BASIC PROGRAMMING COURSE




Fig. 116. Error caused by the insert radius during the execution of a circular interpolation





Fig. 117. Quadrant code defining the radius position with respect to the zero point



CNC - BASIC PROGRAMMING COURSE






Fig. 119. G42: radius tool 0.2, quadrant 3, to the right of the profile

Fig. 118. Quadrant code 0 or 9 for tools offset at the radius center



CNC - BASIC PROGRAMMING COURSE




Fig. 120. G42: radius tool 0.8, quadrant 1, to the right of the profile





Fig. 121. G41: radius tool 0.8, quadrant 2, to the left of the profile



CNC - BASIC PROGRAMMING COURSE




Fig. 122. G41: radius tool 0.2, quadrant 4, to the left of the profile





Fig. 123. Enabling and disabling block outside of the profile



CNC - BASIC PROGRAMMING COURSE





Fig. 124. Drawing of the part to create



CNC - BASIC PROGRAMMING COURSE




11		AX. DRILL D.16	1	1	100.000	120.000	16.000		118.0		
12		ROUGH. BORING-BAR	1	1	86.000	92.000	0.400 ←		93.0	55	8.0

Fig. 125. Data of the new tools to create for the execution of the cycle




CNC - BASIC PROGRAMMING COURSE

1)




- a) G42, quadrant 3
- b) G41, quadrant 3
- c) G41, quadrant 4

2)




- a) G41, quadrant 1
- b) G42, quadrant 3
- c) G42, quadrant 2

3)




- a) G42, quadrant 4
- b) G42, quadrant 2
- c) G41, quadrant 4

4)




- a) G41, quadrant 2
- b) G42, quadrant 2
- c) G41, quadrant 3

5)




- a) G42, quadrant 2
- b) G41, quadrant 2
- c) G42, quadrant 1

6)



- a) G41, quadrant 6
- b) G42, quadrant 3
- c) G42, quadrant 8



CNC - BASIC PROGRAMMING COURSE





Fig. 126. The same right hand rule applies both to the lathe and to the mill.



CNC - BASIC PROGRAMMING COURSE




Fig. 127. Positive direction of the axes: the arrows show the movements of the tool compared to the workpiece




Fig. 128. Vertical mill





Fig. 129. Horizontal mill




CNC - BASIC PROGRAMMING COURSE



Fig. 130. C-axis in a machining center



Fig. 131. B-axis in a machining center



CNC - BASIC PROGRAMMING COURSE




Fig. 132. CAM-generated profile for five-axis machining center





Fig. 133. Programming scheme on plane G17



CNC - BASIC PROGRAMMING COURSE




Fig. 134. Position of the machine zero point and values to enter into the zero offset function for the definition of the part zero point





Fig. 135. Use of TRANS: 1: in a lathe; 2: in a machining center



CNC - BASIC PROGRAMMING COURSE





Fig. 136. 1:Point moved by the NC; 2:Offset value of a mill on the Z-axis




Fig. 137. Measuring system outside the machine



CNC - BASIC PROGRAMMING COURSE



Fig. 138. Start-up of the mill in the training software



CNC - BASIC PROGRAMMING COURSE



Fig. 139. Page for the selection of the tools directly from the magazine




Fig. 140. Completion of the direct tool call instruction in the program



CNC - BASIC PROGRAMMING COURSE

Blank part:	Cylinder
XA:	Cylinder diameter.
ZA:	Position of the upper face of the workpiece referring to the part zero point.
ZI - absolute: - incremental:	Distance from the lower face of the workpiece: referring to the part zero point. referring to the upper face.

Fig. 141. Description of the blank part dimensions: CYLINDER

Blank part:	Pipe
XA:	External diameter of the pipe.
XI:	Internal diameter of the pipe.

Fig. 142. Description of the blank part dimensions: PIPE

Blank part:	Block Centered
W:	Side of the rectangle positioned along the Y-axis.
L:	Side of the rectangle positioned along the X-axis.

Fig. 143. Description of the blank part dimensions: BLOCK CENTERED

Blank part:	Block
X0:	Coordinate X of the edge referring to the part zero point.
Y0:	Coordinate Y of the edge referring to the part zero point.
X1:	Coordinate X of the opposite edge referring to the part zero point (abs.) or to the first edge (incr.).
Y1:	Coordinate Y of the opposite edge referring to the part zero point (abs.) or to the first edge (incr.).

Fig. 144. Description of the workpiece dimensions: BLOCK



CNC - BASIC PROGRAMMING COURSE




Fig. 145. Description of the blank part dimensions: BLOCK

Blank part:	N Corner
N:	Number of edges of the polygon.
SW:	Dimension of the polygon's key (available only for polygons with even number of edges).

Fig. 146. Description of the workpiece dimensions: N CORNER



CNC - BASIC PROGRAMMING COURSE




Fig. 147. Drawing of the part to be created



CNC - BASIC PROGRAMMING COURSE




Fig. 148. Creation of the external profile





Fig. 149. Roughing of the internal profile



CNC - BASIC PROGRAMMING COURSE




Fig. 150. Finishing of the internal profile




Fig. 151. Data entered in drilling cycle



CNC - BASIC PROGRAMMING COURSE





Fig. 152. Graphic 3D image of the finished part



Fig. 153. Discordant cutting direction (left) and concordant cutting direction (right)



CNC - BASIC PROGRAMMING COURSE




Fig. 154. Chip section area





Fig. 155. Relative movement between cutter and workpiece with discordant feed direction



CNC - BASIC PROGRAMMING COURSE




Fig. 156. Cutting forces with discordant feed direction





Fig. 157. Relative movement between cutter and workpiece with concordant feed direction



CNC - BASIC PROGRAMMING COURSE




Fig. 158. Cutting forces with concordant feed direction





Fig. 159. Cutting forces with concordant feed direction



CNC - BASIC PROGRAMMING COURSE




Fig. 160. Cutting forces with concordant feed direction





Fig. 161. Conventional and climb face milling



CNC - BASIC PROGRAMMING COURSE





Fig. 162. Three-dimensional representation of the workpiece



CNC - BASIC PROGRAMMING COURSE





Fig. 163. Drawing of the part to create



CNC - BASIC PROGRAMMING COURSE





Fig. 164. Three-dimensional representation of the workpiece



CNC - BASIC PROGRAMMING COURSE





Fig. 165. Drawing of the part to create



CNC - BASIC PROGRAMMING COURSE




Fig. 166. Three-dimensional representation of the workpiece





Fig. 167. Definition of a point in plane G17 using polar coordinates



CNC - BASIC PROGRAMMING COURSE




Fig. 168. Drawing of the part to create



CNC - BASIC PROGRAMMING COURSE





Fig. 169. Three-dimensional representation of the workpiece



CNC - BASIC PROGRAMMING COURSE




Fig. 170. Drawing of the part to create



CNC - BASIC PROGRAMMING COURSE



Tool list										MAGAZIN1
										
Loc.	Type	Tool name	ST	D	Length	Ø	N	⌀	1	2
1		CUTTER 4	1	1	65.000	4.000	3	⌀	<input type="checkbox"/>	<input type="checkbox"/>
2		FACING TOOL	1	1	120.000	50.000	6	⌀	<input type="checkbox"/>	<input type="checkbox"/>
3		END MILL D20	1	1	105.000	20.000	4	⌀	<input type="checkbox"/>	<input type="checkbox"/>
4		DRILL D10	1	1	100.000	10.000	118.0	⌀	<input type="checkbox"/>	<input type="checkbox"/>
5		MILLING TOOL	1	1	115.000	45.000	4	⌀	<input type="checkbox"/>	<input type="checkbox"/>
6										
7										


Fig. 171. List of tools to be created and used in the test program

Tooling sequence	Tool name	Operation	Cutting speed (m/min)	Feed rate (mm/rev)
1 st	T2 D1	Flattening	100	0.6
2 nd	T5 D1	Cylinder D112	120	0.3 climb milling
3 rd	T3 D1	Pocket D80	90	0.2 climb milling
4 th	T3 D1	Four milling operations	110	0.32
5 th	T1 D1	N2 holes D4	80	0.06
6 th	T4 D1	N4 holes D10	80	0.12


Fig. 172. Sequence of tooling operations and cutting parameters to use for the test



CNC - BASIC PROGRAMMING COURSE



Three-dimensional representation of the workpiece



CNC - BASIC PROGRAMMING COURSE




Fig. 173. Drawing of the part to create

